


TELEPÍTÉS

Mount - Rögzítő



Please read all of the instructions and look at the pictures before attaching the mount.

- 1. Screw a side support onto the flat side of the mount. Attach the foam pads to the mount. Put the charging box into place under the side support. It is important not to position the charging box to close to the AMPS holes.
- 2. Put the other side support in place so it holds the charging box. Screw the side support into place. Place the cable tie in the slot and fasten the charging box and cables. Lay the printer back side up on the table.
- 3. Place the mount onto the printer so the holes match. Attach the mount onto the printer with the four enclosed screws.

For installation onto a pedestal mount: Attach the pedestal mount top plate onto the mount. Attach the printer in place onto the pedestal mount.

4. The mount is in place, with a printer in place.

Az alábbiakkal kompatibilis

Brother TD-2310D; Brother TD-2320D; Brother TD-2320DSA; Brother TD-2320F; Brother TD-2350D;
Brother TD-2350DSA; Brother TD-2350F

